

ENSURE ALL MILES EQUIPMENT IS CLEAN AND DRY PRIOR TO PACKING

PACKING MILES



CLEAN DRY TRANSIT CASE



PLACE THE WEAPONS KEY, MAN (YELLOW) IN AND TURN TO THE ON POSITION



ALL TRANSMITTERS—YELLOW KEY UP



PLACE THE BATTERY BOX ON THE TOP EDGE AND KEEP THE TORSO'S HIGH ALLOWING ROOM FOR THE HELMET HARNESSSES

PACKING MILES



PLACE THE FIRST ROW OF TEN TORSO'S



PACK THE SECOND ROW OF TEN TORSO'S ALSO RESTING THE BATTERY BOX ON THE EDGE AND KEEP THEM HIGH



PACKING OF TWENTY TORSO'S COMPLETE



PLACE THE FIRST TWO HELMET HARNESSSES IN THE UPPER RIGHT CORNER

PACKING MILES



**PLACE THE FIRST ROW OF
TEN HELMET HARNESSSES**



**PLACE THE SECOND ROW
OF HELMET HARNESSSES**



**COMPLETE THE SECOND ROW OF
TEN HELMET HARNESSSES**



**ADJUST THE FIRST ROW
OF TORSO'S**

PACKING MILES



**ADJUST THE SECOND
ROW OF HARNESSSES**



**PACKING OF MILES COMPLETE—ANY
QUESTIONS CALL-751-7521
CALL AND VERIFY TURN IN DAY AND
TIME**